Oil Field Environmental Incident Summary

Responsible Party: Halliburton

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: OLSON 12-1HY

Field Name: VAN HOOK Well File #: 25007

Date Incident: 1/11/2014 Time Incident: 05:00 Facility ID Number:

County: MOUNTRAIL Twp: 150 Rng: 92 Sec: 12 Qtr: SW SE

Location Description:

Submitted By: Jim Raley Received By:

Contact Person:

1801 Burdick Expressway West

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled **Units** Recovered Units Followup **Units** 0 Oil barrels 0 barrels **Brine** 0 barrels 0 barrels Other 20 barrels 20 barrels

Description of Other Released Contaminant:

Hydrochloric Acid

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

No water was impacted or threatened to be impacted. No equipment was damaged and no personal injury occurred as a result of this incident. Impacts are limited to soils on location

Action Taken or Planned:

Acid was neutralized using K-34 (baking soda). Environmental crew was dispatched to remove any impacted soils and replace.

Wastes Disposal Location: At an approved facility-Prarie Disposal

Agencies Involved:

Updates

Date: 1/13/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of hydrochloric acid was contained on location, according to the report. Location is within the MHA Nation. Report forwarded to MHA Environmental and BIA.